

Asbestos Survey Report (Garage)



Site:

Vacant Buildings 9434 Terry Street, Lake, MI 48632 MCE Project No. 70154

Prepared For:

Clare County Land Bank Authority 225 W. Main Street Harrison, MI 48625

Date: August 27, 2024



August 27, 2024

Ms. Jenny Beemer-Fritzinger Clare County Land Bank Authority 225 W. Main St., Harrison, MI 48625

Re: Asbestos Building Inspection Garage on Property 9434 Terry St., Lake, MI 48632 MCE Project Number 70154

Dear Ms. Beemer-Fritzinger,

Delivered by Email

Michigan Consulting & Environmental (MCE) conducted an asbestos inspection at the above referenced property on August 12, 2024. The survey consisted of the interior and exterior portion of a vacant one-story garage building which is approximately 530 square feet (sq. ft.) in size. A second vacant residential building is also located on the site but had previously had an asbestos survey completed on September 29, 2022 by Mid-State Asbestos Removal, Inc. The testing was completed prior to the planned demolition of both buildings on the property.

The sampling was conducted in accordance with the Environmental Protection Agency (EPA) requirements as defined in the Federal Regulation 40 CFR Part 61, Subpart M, National Emissions Standards for Hazardous Air Pollutants (NESHAP) guidelines in order to assess the presence of regulated asbestos containing materials (RACM). This is done by conducting an Asbestos Building Survey prior to renovation or demolition to identify the location and estimate the extent and quantities of asbestos containing material (ACM) present in the survey area. RACM is defined as ACBM that is "Friable asbestos material or non-friable ACM that will be or has been subjected to sanding, grinding, cutting, or abrading or has crumbled, or been pulverized or reduced to powder in the course of demolition or renovation operations."

The survey was completed by Mr. Jacob Cadle, a State of Michigan Accredited Asbestos Building Inspector (Accreditation Number A59674) and Dan Nida a State of Michigan Accredited Asbestos Building Inspector (Accreditation Number A59675). A total of eighteen (18) samples were collected from six (6) different types of homogeneous building materials from the garage, labeled with the abbreviation 9434 MM-(homogeneous material number)-(Sample Number) and abbreviation 9434 TSI (thermal system insultation number)-(Sample Number).

Materials tested included:

- 9434 MM-1: Black Roof Shingle
- 9434 MM-2: White Exterior Siding
- 9434 TSI-1: Grey Insulation
- 9434 TSI-2: Yellow Insulation
- 9434 MM-3: Plywood Siding w/Mastic
- 9434 MM-4: Concrete Floor

Samples were analyzed at Apex Research Incorporated (Apex) for asbestos using polarized light microscopy (PLM) of bulk materials by EPA 600.R-93/116. Apex is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) for the analysis of asbestos in bulk samples by PLM (NVLAP Lab Code 102118-0). A copy of the Apex laboratory analysis report and chain of custody has been included with this letter.

PLM analysis did **not detect** asbestos in any of the samples submitted for analysis.

Thank you for giving MCE the opportunity to provide our services on this project. Please contact me at 269-252-7454 if you have any questions.

Respectfully,

Michigan Consulting and Environmental, Inc.

Jacob Cadle

MI Accredited Building Inspector A59674

Reviewed By

Raymond Brege

Building Inspector A52433

Attachments

Laboratory Analysis Report

KALAMAZOO OFFICE 2800 S. 11th Street, Suite #2 Kalamazoo, MI 49009 Office: 269-547-5295

Laboratory Analysis Report

Apex Research

Test Method, Polarized Light Microscopy (PLM)



08/19/24

Project: 9434 Terry Street, Lake, MI 48632 Project #: 70154.2

Report To:ARI Report #24-112577Mr. Jake CadleDate Collected:08/12/24Clare County Land Bank AuthorityDate Received:08/13/24225 W. Main St.Date Analyzed:08/16/24

Sample Information

Harrison, MI 48625

Asbestos Type/Percent Non-Asbestos Material

Date Reported:

Lab ID #: 112577 - 01 Asbestos Present: **NO** Fiberglass - 30% Cust. #: 9434 MM 1-1 No Asbestos Observed Other - 70%

Material: Location:

Appearance: black, fibrous, nonhomogenous

Black Roof Shingle

Layer: 1 of 1

Lab ID #: 112577 - 02 Asbestos Present: **NO** Fiberglass - 30% Cust. #: 9434 MM 1-2 No Asbestos Observed Other - 70%

Material: Black Roof Shingle

Location:

Appearance: black,fibrous,nonhomogenous

Layer: 1 of 1

 Lab ID #:
 112577 - 03
 Asbestos Present: NO
 Cellulose - 40%

 Cust. #:
 9434 MM 1-3
 No Asbestos Observed
 Other - 60%

Material: Black Roof Shingle

Location:

Appearance: black, fibrous, nonhomogenous

Layer: 1 of 1

For Layered Samples, each component will be analyzed and reported separately.

Robert T. Letarte Jr., Laboratory Director



Test Method, Polarized Light Microscopy (PLM)



08/19/24

Project: 9434 Terry Street, Lake, MI 48632 Project #: 70154.2

Report To:ARI Report #24-112577Mr. Jake CadleDate Collected:08/12/24Clare County Land Bank AuthorityDate Received:08/13/24225 W. Main St.Date Analyzed:08/16/24

Sample Information

Harrison, MI 48625

Asbestos Type/Percent

Asbestos Present: NO

Asbestos Present: NO

Asbestos Present: **NO**

No Asbestos Observed

No Asbestos Observed

No Asbestos Observed

Non-Asbestos Material

Date Reported:

Other - 100%

Other - 100%

Other - 100%

Lab ID #: 112577 - 04

Cust. #: 9434 MM 2-1

Material: White Exterior Siding

Location:

Appearance: white, nonfibrous, homogenous

Layer: 1 of

Lab ID #: 112577 - 05

Cust. #: 9434 MM 2-2

Material: White Exterior Siding

Location:

Appearance: white,nonfibrous,homogenous

Layer: 1 of 1

Lab ID #: 112577 - 06

Cust. #: 9434 MM 2-3

Material: White Exterior Siding

Location:

Appearance: white,nonfibrous,homogenous

Layer: 1 of 1

For Layered Samples, each component will be analyzed and reported separately.

Robert T. Letarte Jr., Laboratory Director



Test Method, Polarized Light Microscopy (PLM)



08/19/24

Project: 9434 Terry Street, Lake, MI 48632 Project #: 70154.2

Report To:ARI Report #24-112577Mr. Jake CadleDate Collected:08/12/24Clare County Land Bank AuthorityDate Received:08/13/24225 W. Main St.Date Analyzed:08/16/24

Sample Information

Harrison, MI 48625

Asbestos Type/Percent Non-Asbestos Material

Date Reported:

Lab ID #: 112577 - 07 Asbestos Present: **NO** Cellulose - 85% Cust. #: 9434 TSI 1-1 No Asbestos Observed Other - 15%

Material: Grey Insulation

Location:

Appearance: grey,fibrous,nonhomogenous

Layer: 1 of 1

 Lab ID #:
 112577 - 08
 Asbestos Present:
 NO
 Cellulose - 85%

 Cust. #:
 9434 TSI 1-2
 No Asbestos Observed
 Other - 15%

Material: Grey Insulation

Location:

Appearance: grey,fibrous,nonhomogenous

Layer: 1 of 1

 Lab ID #:
 112577 - 09
 Asbestos Present: NO
 Cellulose - 85%

 Cust. #:
 9434 TSI 1-3
 No Asbestos Observed
 Other - 15%

Material: Grey Insulation

Location:

Appearance: grey,fibrous,nonhomogenous

Layer: 1 of 1

For Layered Samples, each component will be analyzed and reported separately.

Robert T. Letarte Jr., Laboratory Director



Test Method, Polarized Light Microscopy (PLM)



08/19/24

Project: 9434 Terry Street, Lake, MI 48632 Project #: 70154.2

Report To:ARI Report #24-112577Mr. Jake CadleDate Collected:08/12/24Clare County Land Bank AuthorityDate Received:08/13/24225 W. Main St.Date Analyzed:08/16/24

Sample Information

Harrison, MI 48625

Asbestos Type/Percent Non-Asbestos Material

Date Reported:

Lab ID #: 112577 - 10 Asbestos Present: **NO** Fiberglass - 90% Cust. #: 9434 TSI 2-1 No Asbestos Observed Other - 10%

Material: Yellow Insulation

Location:

Appearance: yellow,fibrous,homogenous

Layer: 1 of 1

Lab ID #: 112577 - 11 Asbestos Present: **NO** Fiberglass - 90% Cust. #: 9434 TSI 2-2 No Asbestos Observed Other - 10%

Material: Yellow Insulation

Location:

Appearance: yellow,fibrous,homogenous

Layer: 1 of 1

 Lab ID #:
 112577 - 12
 Asbestos Present: NO
 Fiberglass - 90%

 Cust. #:
 9434 TSI 2-3
 No Asbestos Observed
 Other - 10%

Material: Yellow Insulation

Location:

Appearance: yellow,fibrous,homogenous

Layer: 1 of 1

For Layered Samples, each component will be analyzed and reported separately.

Robert T. Letarte Jr., Laboratory Director



Test Method, Polarized Light Microscopy (PLM)



08/19/24

Project: 9434 Terry Street, Lake, MI 48632 Project #: 70154.2

Report To:ARI Report #24-112577Mr. Jake CadleDate Collected:08/12/24Clare County Land Bank AuthorityDate Received:08/13/24225 W. Main St.Date Analyzed:08/16/24

Sample Information

Harrison, MI 48625

Asbestos Type/Percent Non-Asbestos Material

Date Reported:

Lab ID #: 112577 - 13 Asbestos Present: **NO** Fiberglass - 90% Cust. #: 9434 MM 3-1 No Asbestos Observed Other - 10%

Material: Plywood Siding

Location:

Appearance: brown, fibrous, homogenous

Layer: 1 of 2

Lab ID #: 112577 - 13a Asbestos Present: **NO** Other - 100%

Cust. #: 9434 MM 3-1 No Asbestos Observed

Material: Mastic

Location:

Appearance: brown,nonfibrous,homogenous

Layer: 2 of 2

Lab ID #: 112577 - 14 Asbestos Present: **NO** Fiberglass - 90% Cust. #: 9434 MM 3-2 No Asbestos Observed Other - 10%

Material: Plywood Siding

Location:

Appearance: brown, fibrous, homogenous

Layer: 1 of 2

For Layered Samples, each component will be analyzed and reported separately.

Robert T. Letarte Jr., Laboratory Director



Test Method, Polarized Light Microscopy (PLM)



08/19/24

Project: 9434 Terry Street, Lake, MI 48632 Project #: 70154.2

Report To:ARI Report #24-112577Mr. Jake CadleDate Collected:08/12/24Clare County Land Bank AuthorityDate Received:08/13/24225 W. Main St.Date Analyzed:08/16/24

Sample Information

Harrison, MI 48625

Asbestos Type/Percent

Non-Asbestos Material

Date Reported:

Lab ID #: 112577 - 14a Asbestos Present: **NO** Other - 100%

Cust. #: 9434 MM 3-2 No Asbestos Observed

Material: Mastic

Location:

Appearance: brown,nonfibrous,homogenous

Layer: 2 of 2

Lab ID #: 112577 - 15 Asbestos Present: **NO** Fiberglass - 90% Cust. #: 9434 MM 3-3 No Asbestos Observed Other - 10%

Material: Plywood Siding

Location:

Appearance: brown,fibrous,homogenous

Layer: 1 of 2

Lab ID #: 112577 - 15a Asbestos Present: **NO** Other - 100%

Cust. #: 9434 MM 3-3 No Asbestos Observed

Material: Mastic

Location:

Appearance: brown,nonfibrous,homogenous

Layer: 2 of 2

For Layered Samples, each component will be analyzed and reported separately.

Robert T. Letarte Jr., Laboratory Director



Test Method, Polarized Light Microscopy (PLM)



08/19/24

Project: 9434 Terry Street, Lake, MI 48632 Project #: 70154.2

Report To: ARI Report # 24-112577 Date Collected: Mr. Jake Cadle 08/12/24 Clare County Land Bank Authority Date Received: 08/13/24 225 W. Main St. Date Analyzed: 08/16/24

Sample Information

Harrison, MI 48625

Asbestos Type/Percent

No Asbestos Observed

No Asbestos Observed

Non-Asbestos Material

Date Reported:

Lab ID #: 112577 - 16 Asbestos Present: NO Other - 100% No Asbestos Observed

Cust. #: 9434 MM 4-1 Material: Concrete Floor

Location:

Appearance: grey,nonfibrous,homogenous

Layer: of

Asbestos Present: NO 112577 - 17 Other - 100% Lab ID #:

Cust. #: 9434 MM 4-2 Concrete Floor Material:

Location:

Appearance: grey,nonfibrous,homogenous

of Layer:

Lab ID #: 112577 - 18 Asbestos Present: **NO** Other - 100%

9434 MM 4-3 Cust. #: Concrete Floor

Material:

Location:

Appearance: grey,nonfibrous,homogenous

Layer: of

For Layered Samples, each component will be analyzed and reported separately.

